

KEYED SHEET NOTES

- 1

L/19 WEeping PIPES WITH WS ON WALLS AND CLGS.
- 2

N.5/20 CITY STORM DRAIN CAUSE OF WATER DAMAGE (HISTORIC)
- 3

L/18.6 FIRE SPRINKLER RISER VMG

GENERAL NOTES

- 1

LCD INSPECTION LOCATIONS ARE APPROXIMATE.

LEGEND

- ACTIVE WATER LEAK
- CURRENT WATER STAINED SURFACE
- HISTORIC WATER LEAK/STAINED SURFACE
- CURRENT MOLD GROWTH
- HISTORIC MOLD GROWTH
- CURRENT WATER ON FLOOR
- HISTORIC WATER ON FLOOR
- DESTRUCTIVE TESTING LOCATION (HISTORIC)
- 325

ROOM NUMBER
- i

LCD INSP. LOCATION NO FINDINGS
- A

LCD INSP. LOCATION ACTIVE LEAK
- B


LCD INSP. LOCATION WATER STAIN
- C

LCD INSP. LOCATION OTHER NOTATION SEE WDA SUMM.
- BC

LCD INSP. LOCATION WITH MULTIPLE FINDINGS "A", "B", OR "C" AS INDICATED



FLOOR PLAN N/E QUADRANT
SCALE: 1/8" = 1'-0"



KEY PLAN

PRIME CONSULTANT



REVISIONS

NO.	DATE	NOTES
11/23/08		DRAFT
12/14/08		FIELD EDITS
12/17/08		FIELD EDITS
2/3/09		FIELD EDITS
2/11/09		FIELD EDITS
2/21/09		FINAL EDITS
2/25/09		FINAL EDITS

CLIENT
STATE OF CALIFORNIA
DEPARTMENT OF GENERAL SERVICES
(DGS NO. 125828)
(AGMT. NO. 3126150)

PROJECT LOCATION
BOARD OF EQUALIZATION BUILDING
450 N STREET
SACRAMENTO, CA. 95814

PROJECT
STATE OF CALIFORNIA, DGS
BOE ASSESSMENT
(LCD NO. 2372-572)

DESCRIPTION
WATER DAMAGE
SURVEY

LOCATION
GROUND
FLOOR

SHT NO.	SHT NAME
2.2	A1.2